


### Bores - reducing space washers



CODE	d mm	D mm	S mm
BSL.001	20	35	6
BSL.002	20	35	10
BSL.003	20	35	20
BSL.004	25	30	4
BSL.005	25	30	6
BSL.006	25	30	20
BSL.007	25	30	40
BSL.008	25	35	6
BSL.009	25	35	10
BSL.010	25	35	20
BSL.011	25	35	30
BSL.012	30	31.75	13.4
BSL.013	30	31.75	15
BSL.014	30	31.75	40
BSL.015	30	35	4
BSL.016	30	35	6
BSL.017	30	35	8
BSL.018	30	35	10
BSL.019	30	35	12
BSL.020	30	35	13.4
BSL.021	30	35	15
BSL.022	30	35	20
BSL.023	30	35	30
BSL.024	30	35	40
BSL.025	30	35	48
BSL.026	30	40	4
BSL.027	30	40	6
BSL.028	30	40	10
BSL.029	30	40	11
BSL.030	30	40	12
BSL.031	30	40	15
BSL.032	30	40	20
BSL.033	30	40	30
BSL.034	30	40	40
BSL.035	30	40	48

CODE	d mm	D mm	S mm
BSL.036	30	50	10
BSL.037	30	50	20
BSL.038	30	50	30
BSL.039	30	50	48
BSL.040	30	50	50
BSL.041	32	50	40
BSL.042	32	50	60
BSL.043	35	40	4
BSL.044	35	40	6
BSL.045	35	40	8
BSL.046	35	40	10
BSL.047	35	40	12
BSL.048	35	40	15
BSL.049	35	40	20
BSL.050	35	40	30
BSL.051	35	40	40
BSL.052	35	40	48
BSL.053	35	50	10
BSL.054	35	50	20
BSL.055	35	50	30
BSL.056	40	50	10
BSL.057	40	50	20
BSL.058	40	50	30
BSL.059	40	50	48